

Work Order ID 57290

Wednesday, March 31, 2010 3:36:28 PM

Page 1

Item ID: D3284-009

Accept

Setup Start

Revision ID:

Stop

Item Name: Bearing

Start Date: 3/31/2010 Start Qty: 1.00

Cust Item ID:

Required Date: 3/31/2010 Req'd Qty: 1.00

Customer:

Reference: Return 2010 / RA110017

Run Start

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Stop

QC: *J* Date: 10-31 SPC (Y/N): _____ Date: _____

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	----------------	--------------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3284	Rev A

100	QC5- Inspect part completeness to step on W/O	0.00
-----	---	------



QC

Quality Control

Memo

Original B54997. Part is good.

0.00

*S 10/04/01**(71)*

110	Identify as per dwg & Stock Location: <i>Stoys</i>	0.00
-----	--	------



Packaging

Packaging

Memo

Identify with the new batch # & return to stock.

0.00

P 12/4/05 (1)

120	QC21- Final Inspection - Work Order Release	0.00
-----	---	------



QC

Quality Control

Memo

0.00

*10/04/06**MF**10-4-5*